Update Advisory Site Supervisor 2.02F01

Release Notes

A new general release version of the Site Supervisor controller firmware, version 2.02F01, has been released and is available for customer upgrade. For more information, visit the Site Supervisor page on the Emerson Climate Technologies Retail Solutions Web site: **http://www.emersonclimate.com/en-us/Products/Controls/ Facility_Controls/Pages/Site-Supervisor.aspx**

SITE MANAGER UPDATE REQUIRED

Site Supervisor requires Site Manager 16.3 or greater. If communication with Site Manager is required, upgrade Site Manager to version 16.3 first, then update the Site Supervisor controllers. Contact Emerson Retail Solutions for more information about upgrading.

Site Supervisor 2.02F01 Adds the Following Features and Enhancements:

Feature Descriptions	Supported in Site Supervisor 2.02F01
E2 to Site Supervisor Peer Alarming	✓
E2 to Site Supervisor Global Data	✓
Smart Alarming (Licensed Feature)	✓
Enabled Push Button Selections	✓
Run Time Log Viewing For Expanded Information	✓
Case Defrost Summary	✓
Condenser Control, XM Circuit, and Suction Group Associations	✓
Application/Device Details - UI Performance Tuning for 10" Display	✓
SD Card or USB Drive Backup and Restoration	✓
ADF File Removal	✓
Site Supervisor Support in UltraSite (Terminal Mode Only)	✓
Ability to Remote Upgrade Firmware of 4.3" Display	✓
Display Icon and Status Consistency on 4.3" Display	✓
Display Page and Optimization on 4.3" Display	✓
Fix Descriptions	**Supported in Site Supervisor 2.02F01**
Licensing - Lighting Application - Increased the Number of Lighting Applications to Six (6)	✓
Event Scheduling - Override Option has Been Added to Time Scheduling	✓
The Bypass tab or Bypass Properties are no Longer Missing in Some Applications	✓
Display - Items of a Category in the 4.3" Display are Now Consistent with those in the Site Supervisor Web Interface when the Category of an Application is Changed	✓
RF Module - Offset Option is Now Available for Sensors	✓
Analog Combiner - "Temperature" is Now the Default Value of Eng Units	✓
RCB - Heat and Cool Stages Now Appear in Order on the Outputs Tab	✓
CCTStat - Default Network Summary Properties Heat 1, Heat 2, and Cool 1, Cool 2 are in the Summary Screen	✓
Enhanced Suction - Critical Alarms Monitoring is Set to **Yes** by Default	✓
Suction Groups - Critical Alarms Monitoring is Set to **Yes** by Default	✓
4.3" Display - Store Managers Have Permissions to Change the HVAC Setpoints	✓

Table 1 - Site Supervisor 2.02F01 Feature/Fix Matrix

Who Should Update

Emerson Retail Solutions recommends that all customers upgrade their Site Supervisor controllers and PCs running Site Manager to the latest version to take advantage of the latest fixes and enhancements listed above.

All customers who meet one or more of the requirements below are advised to upgrade to Site Supervisor 2.02F01:

- **Customers using any of the features listed in Table 1.**

Documentation Updates

- **026-1800 Rev 5 - Site Supervisor User Guide**

Site Manager Compatibility

Version Compatibility	
Site Manager Version	**Site Supervisor 2.02F01 and above**
16.3	✓

Table 2 - Site Manager Compatibility Matrix

For Emerson Retail Solutions Technical Support

- 770-425-2724
- SolutionsTechSupport@EmersonClimate.com

EMERSON. CONSIDER IT SOLVED.